

# DH-PFA10C

## Mount Adapter



- · Aluminum alloy material
- · Matched with particular cameras, beautiful and elegant designed







#### Scene

Suitable for camera mounting with operating temperature from  $-40^{\circ}$ C to  $+60^{\circ}$ C ( $-40^{\circ}$ F to  $+140^{\circ}$ F) and relative humidity less than 90%.

Technical Specification	
Model	DH-PFA10C
Material	Aluminum alloy
Dimensions	166.0 mm $\times$ 166.0 mm $\times$ 83.5 mm (6.53" $\times$ 6.53" $\times$ 3.29") (L $\times$ W $\times$ H)
Weight	0.43 kg (0.95 lb)
Load Bearing	3.0 kg (6.61 lb)
Operating Temperature	-40°C to +60°C (-40°F to +140°F)
Operating Humidity	<90% (RH)
Color	White
Applicable Camera	Please see "Accessory Selection"

Ordering Information		
Туре	Model	Description
Camera Mount	DH-PFA10C	Mount Adapter

#### Installation



### Dimensions (mm[inch])



